To: "Sharon Budney" [BudneySL@cdm.com]; tephanie Vaughn/R2/USEPA/US@EPA[] Cc: "Doug Simmons" [doug.simmons@aecom.com]; Willard Potter" [otto@demaximis.com] From: "Robert Law" Sent: Tue 9/18/2012 11:54:43 AM Subject: 2012 Bathymetry Survey - Daily Status Report for September 17, 2012 9-17 coverage.kmz 20120917 Coverage.kmz
Daily Status Report for Monday September 17, 2012
Work Completed Today:
Multi Beam Survey
Multi beam survey operations were completed today with the completion of the remaining sections between RM 7.1 and the Clay Street Bridge and with conducting the final patch and performance tests.
The attached coverage plot (KMZ) file shows the extent of the survey performed today.
Single Beam Survey
The single beam survey operations today included completing the RM 7.50 to RM 7.80 area and initiating work in the RM 7.10 to RM 7.50 area.
The attached coverage plot (KMZ) file shows the extent of the survey performed today.
Work Planned for Tomorrow:
Single beam survey operations planned for tomorrow include continuing survey operations in the RM 7.10 to RM 7.50 area.

Deviations from the QAPP:		
None noted.		
Health and Safety Issues:		
None noted.		